## **Advanced Stone Setting - Pave and Thread Work**

Students will need the following tools:

- Optivisor with 2.5x lens
- 10X Jeweler's Loupe
- Stone Burnisher (can make a simple one in class)
- Assorted Gravers with handles:

Flat: (#37, #39, #42) Onglette: (#0, #2) Round: (#51, #53) V-point: (105°, 120°)

Assorted Burrs:

Ball (2.7mm, 2.9mm, 3mm) Setting (2.9mm, 3mm) Hart (2.9mm, 3mm)

- Beading Tools: (#9, #10, #11)
- 2" x 2" x 1/16" Copper practice plates (2)
- 1.5mm drill bits
- 3mm round precision machine cut faceted stones Pack of 100 (CZ recommended)